

CM-03

AC Leakage Current Tester

UL CE CAT II 600V, CAT III 300V

Features:

- Accurate AC digital clamp meter for leakage current measurement
- AC current measurement: 0 ~ 60A
- AC voltage measurement: 0 ~ 400V
- 10µA ultra high resolution on 40mA range
- Shield transformer jaws to minimize the effect of external stray magnetic field.
- Large jaw with **30 mm** diameter.
- ACA Five Ranges (40mA, 400mA, 4A, 40A, 60A) for all application.
- A filter circuit is designed to eliminate the effect of high frequency noise and harmonics for AC current measurement.
- Large 3 3/4 digits LCD
- Fast bargraph display (**30 times**/sec.) for transient observation.
- **Continuity** and **Frequency** measurements.
- Max/Min, Data Hold functions, and Relative Measurement
- Easy single rotary switch for any function selection
- 600V overload protection for ohm measurement

Electrical Specifications: (23°C±5°C)

AC Current:

Range	Resolution	Accuracy		Remarks
		50/60 Hz	Wide	
			(40 - 1KHz)	
40mA	10μΑ	±1.0%±3dgts	±2.0%±5dgts	
400mA	100μΑ	±1.0%±3dgts	±2.0%±5dgts	
4A	1mA	±1.0%±3dgts	±2.0%±5dgts	
40A	10mA	±1.0%±3dgts	±2.0%±5dgts	
60A (0-50A)	100mA	±1.5%±3dgts	±3.0%±5dgts	
60A (50 - 60A) ¹	100mA	±3.0%±5dgts	±3.5%±5dgts	

¹ Though the meter can display up to 400A, it is not calibrated beyond 60A.



AC Voltage:

(Input Impedance: $10M_{\Omega}$)

Range	Resolution	Accuracy		Overload Protection
		50/60 Hz	40 - 1KHz	
400V	0.1V	±1.5%±2dgts	±2.0%±4dgts	AC 800V

Resistance (Ω) and Continuity:

(open voltage 0.4V)

Range	Resolution	Accuracy	Beeping	OL Protection
$40\text{-}400\Omega$	0.1Ω	±1.0%±2dgts	< 38.0 Ω	AC 600V

General Specifications:

Conductor Size:	30mm max. (approx.)		
Battery Type:	two 1.5V SUM-3		
Display:	3 3/4 LCD with 40 seg. bargraph		
Range Selection:	manual		
Overload Indication:	OL		
Power Consumption:	15 mA (approx.)		
Low battery Indication:	B		
Sampling Time:	3 times/sec. (display)		
	30 times/sec. (bargraph)		
Auto-Power-Off:	15 minutes		
Operating Temperature:	-10°C to 50°C		
Operating Humidity:	less than 85% relative		
Storage Temperature:	-20°C to 60°C		
Storage Humidity:	less than 75% relative		
Altitude:	up to 2000M		
Dimension:	210mm (L) x 62.0mm (W) x 35.6mm (H)		
	8.3" (L) x 2.4" (W) x 1.4" (H)		
Weight:	200g (battery included)		
Accessories:	Carrying bag x 1		
	Users manual x 1		
	1.5V battery x 2		
	Test leads x 1		

PROVA INSTRUMENTS INC.

Add: 6F-2, No. 129, Lane 235, Pao-Chiao Road, Shin-Tien District,

New Taipei City 23145, TAIWAN

Tel: 886-2-89191255

E-mail: prova@ms3.hinet.net

